



## STARTING FITTINGS FOR K-6519, 6710 & K-6910 RAIL PROFILES




K-7530 K-7730 K-7930 Left Hand Volute	K-7535 K-7735 K-7935 Right Hand Volute	K-7540 K-7740 K-7940 Left Hand Turnout	K-7545 K-7745 K-7945 Right Hand Turnout	K-7510 K-7710 K-7910 Starting Easing with Newel Cap	K-7519 K-7719 K-7919 Opening Cap	K-7533 K-7733 K-7933 Left Hand Ascending Volute	K-7536 K-7736 K-7936 Right Hand Ascending Volute
---	--	--	---	---	---	---	--

## TRANSITION FITTINGS FOR K-6519, 6710 & K-6910 RAIL PROFILES




K-7509 K-7909 Returned End	K-7511 K-7711 K-7911 Level Quarterturn 90°	K-7512S K-7712S K-7912S Up Easing	K-7513 K-7713 K-7913 Over Easing	K-7514S K-7714S K-7914S Up Easing 90°	K-7520 K-7720 K-7920 Tandem Cap	K-7521 K-7721 K-7921 Quarterturn Cap 90°	K-7521-135 K-7721-135 K-7921-135 Level Cap	K-7522-L K-7722-L K-7922-L 5" Center to Center (LH shown)	K-7522-R K-7722-R K-7922-R
-------------------------------------	--	--	---	--	--	--	---	---	----------------------------------

## GOOSENECK FITTINGS FOR K-6519, 6710 & K-6910 RAIL PROFILES



K-7550 K-7750 K-7950 Left Hand 2 Riser No Cap 90°	K-7555 K-7755 K-7955 Right Hand 2 Riser No Cap 90°	K-7560 K-7760 K-7960 Left Hand 2 Riser With Cap 90°	K-7565 K-7765 K-7965 Right Hand 2 Riser With Cap 90°	K-7561 K-7761 K-7961 Left Hand 2 Riser With Cap 45°	K-7566 K-7766 K-7966 Right Hand 2 Riser With Cap 45°	K-7571 K-7771 K-7971 Left Hand 2 Riser No Cap 90°	K-7576 K-7776 K-7976 Right Hand 2 Riser No Cap 90°
---	--	---	--	---	--	---	--



K-7581 K-7781 K-7981 Left Hand 2 Riser With Cap 90°	K-7586 K-7786 K-7986 Right Hand 2 Riser With Cap 90°	K-7589 K-7789 K-7989 2 Riser Tandem Cap	K-7597 K-7797 K-7997 2 Riser With Cap	K-7599 K-7799 K-7999 2 Riser No Cap
---	--	--	--	--

### HOW TO ORDER FITTINGS

The second digit of the fitting part number must match the second digit of the rail part number.

Example:

K-75XX Fitting = K-6519 Rail  
K-77XX Fitting = K-6710 Rail  
K-79XX Fitting = K-6910 Rail